

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/04/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/03/12 – 0700, 05/10/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Ceresco Dam legacy work, oil globs and sheen observed during legacy work. • Ceresco Dam control point, sheen observed. • Ceresco Dam, sheen observed. • MP10.75, sheen observed. • Observed buoy installed at 10.75 sediment trap location. • MP10.75, sheen observed. • Rock Tenn, sheen observed. • MP21.5, sheen observed throughout boomed area. • MP21.5 RDB just prior to Custer Drive bridge, sheen observed. 		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			